

AMENDMENT TO DRAWING FIGURES:

Originally filed Figures 67 and 69 show specially shaped ends on the piezoelectric elements that make it easier to press-fit the piezoelectric elements into openings in the resonator. That feature is not relevant to the present claims. Figures 67 and 69 show an electrical connection that has an incorrect connection among adjacent piezoelectric elements. These figures are not needed for antecedent basis on the correct interconnection of piezoelectric elements, as that connection is well known to one skilled in the art, and the erroneously depicted connection of Figures 67 and 69 are believed to be apparent to one skilled in the art. Revised Figures 67 and 69 are submitted herewith showing the correct electrical interconnection, with the changes circled in red. No new matter is added. Because Figure 68 appears on the same sheet, it is included, but is not changed.

Approval of the drawing change is respectfully requested.

The formal drawings submitted herewith contain the revisions to Figures 67 and 69.




Fig. 67




Fig. 68




Fig. 69

REMARKS

If any additional fee is required, please charge Deposit Account Number 19-4330.

Respectfully submitted.

STETINA BRUNDA GARRED & BRUCKER

Date: 10/22/03
Customer No.: 007663

By: Lowell Anderson
Lowell Anderson
Registration No. 30,990
75 Enterprise, Suite 250
Aliso Viejo, CA 92656
(949) 855-1246
Fax: (949) 855-6371

T:\Client Documents\ellip\002c\Prelim Amend.doc